

Pre-buy Spec Sheet
Data subject to change prior to finalization.

| PT6A-114A SN PCE-PC2131 | | | | | |
|-------------------------|--------------|--|--|--|--|
| Value | Times/Cycles | | | | |
| TTSN | 4,595.6 | | | | |
| TCSN | 7,652 | | | | |
| TSO | 0 | | | | |
| CSO | 0 | | | | |
| TSHSI | 0 | | | | |

OH by MTS- April 2024 HSI by MTS- April 2024 POST SB1749

| Part Number | Description | Serial Number | Total Cycles | Cycle Limit | Cycles Remaining |
|-------------|--------------|---------------|--------------|-------------|------------------|
| 3013111 | Rear Hub | RWA47E723 | 7,652 | 19,000 | 11,348 |
| 3013712 | #2 Comp Disc | 0174 | 12,171 | 24,000 | 11,829 |
| 3011713 | #3 Comp Disc | 5F824 | 11,121 | 25,000 | 13,879 |
| 3027798 | Impeller | TXA1D2959 | 7,652 | 19,000 | 11,348 |
| 3013411 | CT Disc | CRAZAEQE506 | 7,652 | 16,000 | 8,348 |
| 3026812 | PT Disc | YUAB001C506 | 7,652 | 20,000 | 12,348 |
| 3079351-01 | CT Blades | N/A | TSN: 4,595.6 | | |

| Part Number | Description | Serial Number | TSO |
|---------------|------------------|---------------|-----|
| 8210-002-01 | Prop Governor | 19740857 | 0 |
| 702801-5 | Fuel Pump | 003743 | 0 |
| 3244897-3 | FCU | B10849 | 0 |
| 10552E | Oil/Fuel Heater | WA50289 | 0 |
| Not Installed | Ignition Exciter | Not Installed | 0 |
| 3049038-03 | Comp Bleed Valve | 8145 | 0 |
| 3019906 | Start Control | L0747 | 0 |

Contact Info:

Cell Phone: 254-242-6840

Email: sales@dunkinaviationsolutions.com

ALL DATA COMPILED IN THE CREATION OF THIS REPORT IS FOR REFERENCE ONLY AND NOT TO BE USED AS THE SOLE CRITERIA FOR MAINTAINING CONTINUED AIRWORTHINESS.

THE ENGINE LOGBOOK MUST BE USED FOR FINAL DETERMINATION OF AIRWORTHINESS AND TO CONFIRM TIMES AND CYCLES OF ENGINE AS WELL AS ALL PARTS AND ACCESSOIRES.

5/29/2024 Final